Unauthorized Disposal of Construction Waste and Contaminated Soils in Quebec: A Symptom of the Provincial Regulatory Body's Inadequate Monitoring and Enforcement

Alex DePani, B.A. Hon. Economics
Under the supervision of
Prof. Colin Scott, Dept. of Anthropology











June 19th 2020 - Satellite Imagery of the Property After the Opening of the Sorting Center, eighteen months after the first observed infraction

June 1st 2021 - Satellite Imagery of the Property one Month Before the Provincial Regulatory Body's Ordinance

May 8th 2023 - Satellite Imagery of the Property One Year After the Revocation of the Sorting Center's Permit



Acknowledgments

This research project was funded by Dr. Leah Pope, Mr. Clayton Pope as well as the *Leadership for the Ecozoic* research group. Without their generous contributions, this learning experience would not have been possible.

Community Collaboration

- Spending time with key local community stakeholders in the Chateauguay River watershed, such as mayors or union representatives, to discuss how academic research can help promote sustainable livelihood in their region.
- Cause for concern: local groundwater's integrity after years of unauthorized backfilling of construction waste and contaminated soils.
- Keeping continuous contact with community stakeholders throughout the research process to make sure academic research maintains its utility for the local community.

Systematic Issue in the Greater Montreal Area and its Surroundings

- Management of construction waste and contaminated soils: a provincial jurisdiction.
- Systematic overview of all ordinances issued by the provincial regulatory body in the past thirteen years.
- Identification of publicly available documents reviewing violations revolving around unauthorized disposal of soils contaminated by construction waste.
- Concentrations of petroleum hydrocarbons, polycyclic aromatic hydrocarbons and heavy metals exceeding legal thresholds on most unauthorized sites.
- Fines and warnings issued by the provincially regulatory body often ignored by offenders.
- Average delay of approximately four years between the first on-site inspection by the provincial regulatory body and the issuance of an ordinance.

Case Study

- In-depth analysis of an ongoing court case happening in the watershed.
- Excavation firm with legal precedents backfilled contaminated soils on a private property.
- Local municipality seeking removal of contaminated soils at the property owner's expense.
- Complex legal dynamics to decide who will be held liable.

Ordinance Follow-Up

- Request for access of information never answered by the provincial regulatory body.
- Intertemporal mapping of unauthorized disposal sites that received an ordinance.